

451
36

T0750" C05T2860




Fig. 1A
(PRIOR ART)




Fig. 1B
(PRIOR ART)




Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6A




Fig. 6B





Fig. 7

HIGH PRESSURE SPRAY BAR
DEFECT DENSITY RESULTS
DEVICE 21841 - 0.35u



15.15% AVERAGE
REDUCTION IN
DEFECT DENSITY

Fig. 8